

ANNUAL SURVEYS.

11311

Rec'd 20 Jan

No. 445 Survey held at London Date 17 Jan 1845
 on the S Woodbridge Master Dobson
 Tonnage 576 Built at Chelmsford When built 1809
 By whom built Owners Tibbitt & Co
 Port belonging to London Destined Voyage Aden
 If Surveyed Afloat or in Dry Dock Afloat had been in dry dock

Last Survey, No. 4035 Port of London Classed A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>as when seen</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper 1843 <u>good</u>

General Observations and Opinion, Fastenings are firm & secure and the apparatus
 as required by the Instructions, is in an efficient condition for the conveyance of any and
perishable Cargos to & from all parts of the world and
 Committee Minute 24 Jan 1845

Character assigned A1 may remain as Classed
Hourtson

No. 532 Survey held at London Date 17 January 1845
 on the M Puckers Master Nelson
 Tonnage 329 Built at London When built 1829
 By whom built Hawke Owners Cruikshank
 Port belonging to London Destined Voyage To Vincent
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 1079 Port of London Classed A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper 1844 <u>good</u>

General Observations and Opinion, Is in good efficient condition and may
 as required by the Instructions, remain as Classed

Committee Minute 24 Jan 1845

Character assigned A1



© 2019

Lloyd's Register
Foundation

LON 618-0327