

ANNUAL SURVEYS.

11317

Rec 28 Jan

No. 243 on the Bark "Oliza" Survey held at London Date 24th Dec 1845 Master Wm Jones
 Tonnage 340 Built at Nova Scotia When built 1841
 By whom built Owners Foster & Co
 Port belonging to St Vincent Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock in Carters Dock

Last Survey, No. 10418 Port of London Classed 4 A 1

The Surveyor is required to state the present Condition of the

Decks	Good	Transoms	New Wing transoms of dautye for new fashion timber	Capstan	Good
Upper Deck Beams & Fastenings	—	Timbers of the Frame	Good	Pumps	—
Lower Deck Beams & Fastenings	—	Topsides	—	Masts, Yards, &c.	New for Mast and boust for new good
Spirkettling	—	Wales	Caulked Good	Sails	Sufficient
Plank Shears	Caulked	Counter	—	Cables	—
Waterways	—	Plank and Treenails	Good	Anchors	No. of 20 15 1 K
Hatchway Comings	—	(Outside to the Water's Edge.)	—	Standing & Running Rigging	Overhauled 1844
Breasthooks	—	Rudder	—	Copper	1844 Satches Good
		Windlass	—		

General Observations and Opinion, at Present several (8) after hoods of the bottom plank as required by the Instructions, on both sides have been removed a new wing transom of dautye for ~~new~~ fine stern timber and part new fashion timber have been fitted, caulked from the Copper to the waterways and Committee Minute 24th Jan 1845 the Copper has been satches - The now Character assigned 4 A 1 appears in efficient Condition and may remain as Classed 4 A 1

W. H. Hatcher

No. 504 on the Ship "City of Poona" Survey held at London Date 10th Jan 1845 Master Wright
 Tonnage 557 Built at Cochin When built 1838
 By whom built Owners R Green
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock in Mr Greens Dock

Last Survey, No. 10437 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Caulked Good	Transoms	Good	Capstan	Good
Upper Deck Beams & Fastenings	Good	Timbers of the Frame	—	Pumps	—
Lower Deck Beams & Fastenings	—	Topsides	—	Masts, Yards, &c.	Sufficient
Spirkettling	—	Wales	Caulked	Sails	—
Plank Shears	Caulked	Counter	—	Cables	—
Waterways	—	Plank and Treenails	—	Anchors	No. of —
Hatchway Comings	—	(Outside to the Water's Edge.)	—	Standing & Running Rigging	—
Breasthooks	—	Rudder	—	Copper	1843 Metal Satches
		Windlass	Riding bolts Good		

General Observations and Opinion, at Present Caulked all over from Copper up as required by the Instructions, both decks Caulked - Chain bolts renewed and ship generally overhauled - Is in most efficient Condition and may remain as Classed 12 A 1

Committee Minute 24th Jan 1845

W. H. Hatcher