

# ANNUAL SURVEYS.

11385

No. 37 Survey held at London Date Feb 26 1845  
 on the Bk Vertumnis Master J Thomson  
 Tonnage 315 Built at Sunderland When built 1843  
 By whom built \_\_\_\_\_ Owners Shelshear  
 Port belonging to London Destined Voyage St Petersburg  
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 2508 Port of Sunderland

Classed 8A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Is throughout in a good & efficient state to retain  
 as required by the Instructions, her present class

Committee Minute 28th Feb 1845

Character assigned 8A1

No. 523 Survey held at London Date Feb 27 1845  
 on the Bk Mary Ann Master Guy  
 Tonnage 201 Built at Spewick When built 1830  
 By whom built \_\_\_\_\_ Owners Crisp  
 Port belonging to London Destined Voyage Algoa Bay  
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 10434 Port of London

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>on August 1842</u>

General Observations and Opinion, At the present time caulked from the upper to the  
 as required by the Instructions, gunwale and two pair of iron hanging knees to the  
midship deck beams and is in all respects in an  
efficient state to continue on her present class

Committee Minute 28th Feb 1845

Character assigned 12A1