

REPORT of SURVEY for REPAIRS.

11409

No. 58 Survey held at London Date March 1845
 on the W. Camilla Master Bunny
 Tonnage 383 Built at Newcastle When built 1829
 By whom built Owners Burton
 Port belonging to London Destined Voyage W Indies
 If Surveyed Afloat or in Dry Dock Afloat
 Last Survey, No. 10634 Classed 12
 Port London Cont. 41 — 4

PAIRS

Several pieces of planks shifted in the upper works the
 black strokes and topsides being partially new & made
 before the work was done and the repair
 completed from the sides up

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do when seen</u>	Capstan <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Pumps <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Masts, Yards, &c. <u>Apparent</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Sails <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge)	Cables <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Anchors No. of <u>do</u>
Breasthooks <u>do</u>	Copper <u>Good</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

In the parts where the planks were shifted the
 timbers proved to be good and the appars in an efficient
 state and may remain as classed

The Amount of Fee £100 is received by me,

Committee's Minute 18 March 1845

Character assigned Cont 41



© 2019

Lloyd's Register
Foundation

LON 618-0424(20)

Last Survey, No. 19034

Port

London

LONG 618-0424(1/2)

31 Mar 45

Lon. 11409

The "Camilla" canney is a
ship & not a barge

before. The woman who has