

ANNUAL SURVEYS.

11433

R. 22 Mar 1845

No. 16 Survey held at London Date 18th March 1845
 on the M^r Waterman Master Dodd
 Tonnage 355 Built at Null When built 1825
 By whom built - Owners Brookbank
 Port belonging to London Destined Voyage Liverpool
 If Surveyed Afloat or in Dry Dock Afloat and in Dry Dock

Last Survey, No. 9635 Port of London Classed F. 1

The Surveyor is required to state the present Condition of the

Decks <u>Very good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>in the best</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,
 as required by the Instructions, Masts topsides & caulked she appears in a good
and substantial condition for for the conveyance of any and
perishable Cargos and may remain as classed
 Committee Minute 25th March 1845
 Character assigned F. 1 Hourtenay

No. 880 Survey held at London Date 18th March 1845
 on the M^r Boyle Master -
 Tonnage 597 Built at Cherbourg When built 1817
 By whom built - Owners Ward
 Port belonging to London Destined Voyage Liverpool
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9643 Port of London Classed F. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>in the best</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,
 as required by the Instructions, She appears in good and efficient condition
for for the conveyance of any & perishable Cargos and may remain
as classed
 Committee Minute 25th March 1845
 Character assigned F. 1 Hourtenay

