

ANNUAL SURVEYS.

11434

Re 224 Wm

No. 950 Survey held at London Date March 8 1845
 on the Bk Mona Master Samson
 Tonnage 396 Built at Isle of Man When built 1833
 By whom built _____ Owners Glass & Co
 Port belonging to Singapore Destined Voyage Algoa Bay
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 5899 Port of Liverpool Classed A.1
 Cont. 40 2

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Well found</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper <u>"</u>
	Windlass <u>"</u>	

General Observations and Opinion, I am of opinion the vessel is in good condition for the safe
 as required by the Instructions, conveyance of dry & perishable cargoes but not on that
efficient state to be classed A.1 Arthur

Committee Minute 25th March 1845
 Character assigned A.1 LD W. Martin

No. 127 Survey held at London Date March 10th 1845
 on the Ada Master Custance
 Tonnage 127 Built at London When built 1844
 By whom built 1844 Owners _____
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwood Dock

Last Survey, No. 11088 Port of London Classed 11A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u>	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper <u>"</u>
	Windlass <u>"</u>	

General Observations and Opinion, Caulked from the Copper overalls and is in an efficient state
 as required by the Instructions, to retain her present class

Committee Minute 25th March 1845
 Character assigned 11A1 LD W. Martin