

ANNUAL SURVEYS.

17526

No. 802 Survey held at London Date April 8th 184 5
 on the By Crusader Master Palastter
 Tonnage 150 Built at Jersey When built 1828
 By whom built Jersey Owners Abrown
 Port belonging to Jersey Destined Voyage —
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 4413 Port of Spain

Classed F. 11

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>efficient</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>the whole</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>pt capt</u>

General Observations and Opinion,

as required by the Instructions,

She appears in good and efficient condition for the conveyance of dry & perishable cargoes to & from all parts of the world and may remain as classed

Committee Minute 2nd May 1845

Character assigned

12 A 1 Hourton

No. 130 Survey held at London Date April 12th 184 5
 on the Mc Caroline Master Didan
 Tonnage 244 Built at London When built 1841
 By whom built Green Owners Hanky
 Port belonging to Pennam Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11079 Port of London

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>efficient</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>the whole</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Yellow Metal upon</u> 1845

General Observations and Opinion,

as required by the Instructions,


Tripped bottom Coulted, sheathed with yellow metal upon paper, false Red made good a pair of diagonal Rodies a pair of quarter buks, a pair of slope Standards & 2 pairs of hanging Ropes to Starboard Dick.

Committee Minute 2nd May 1845

Character assigned

12 A 1 in an efficient condition

Special Damage £3.3



© 2019

Lloyd's Register Foundation

100618-0538