

ANNUAL SURVEYS.

11530
16.5.1845

No. 215 Survey held at London Date May 24th 1845
 on the Ship "Benjamin Greene" Master Law
 Tonnage 318 Built at Sunderland When built 1838
 By whom built 405 Owners Greene & Son
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Keeps Dry Dock

Last Survey, No. 9803 Port of London Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

Had grown old on her last voyage but sustained no damage beyond the forcing off part of false keel now with few sheets of yellow metal made good is in an efficient condition and may remain as classed Fourteen

Committee Minute 16th May 1845

Character assigned

Special Damage £2.2

No. 215 Survey held at London Date 21 April 1845
 on the Ship "Hebrides" Master Melville
 Tonnage 572 Built at Greenock When built 1841
 By whom built 646 Owners Dennistoun
 Port belonging to Greenock Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 9803 Port of London Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>ed abroad 1844 224200L</u>

General Observations and Opinion,

as required by the Instructions,

Is in an efficient condition and may remain as classed - Had to have grown and and shipped and dropped at Singapore in the last year bottom then caulked

Committee Minute 16th May 1845

Character assigned

Special Valuation £5.5.0

