

ANNUAL SURVEYS.

11570

No. 10595 Survey held at London Date 26th May
 on the Mt Sappho Master Dunlop
 Tonnage 368 Built at Guernsey When built 1840
 By whom built 446 Owners Balderston & Co
 Port belonging to Guernsey Destined Voyage China
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 10595 Port of London Classed GA

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Seem</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Yellow Metal Port & Portholes</u>

General Observations and Opinion,

as required by the Instructions, Caution from the keel to the wales the sheer
tricky stations need upoint and sheathed with yellow

Committee Minute 9 May 1845

Character assigned GA
record of m. to
Special Damage £3.3

Metal upon felt & paper
is in an efficient condition
and may remain as Classed
Fourteen
Stitching

No. 11009 Survey held at London Date 7 May
 on the Mt Manding Master
 Tonnage 217 Built at Sunderland When built 1827
 By whom built Owners Curling & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11009 Port of London Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Seem</u>	Timbers of the Frame <u>do when seen</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, She is in an efficient condition fit for the
conveyance of dry and perishable cargo to & from all

Committee Minute 9 May 1845

Character assigned GA
and asterisk
may remain as Classed

W.B.

© 2019 Lloyd's Register Foundation