

# ANNUAL SURVEYS.

11502  
Recd 15 May

No. 136 Survey held at London Date 14 May 1845  
on the Barque "Cyprus" Master Sprattley  
Tonnage 281 Built at America When built  
By whom built Owners W. & Co  
Port belonging to London Destined Voyage South Sea Fishery  
If Surveyed Afloat or in Dry Dock in Mr. Lee's Dock & in the East Country Dock

Last Survey, No. 4112 Port of London

Classed \*A expunged  
3d

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>-</u>	Timbers of the Frame <u>-</u>	Pumps <u>over hauled</u>
Lower Deck Beams & Fastenings <u>-</u>	Topsides <u>scrapped &amp; refitted</u>	Masts, Yards, &c. <u>new for &amp; again hauled</u>
Spirketting <u>-</u>	Wales <u>Caulked</u>	Sails <u>sufficient &amp; new</u>
Plank Shears <u>-</u>	Counter <u>new</u>	Cables <u>new</u>
Waterways <u>-</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>3 B 14 1 12</u>
Hatchway Comings <u>-</u>	Rudder <u>partly new</u>	Standing & Running Rigging <u>refitted</u>
Breasthooks <u>-</u>	Windlass <u>Good</u>	Copper <u>new 1845</u>

General Observations and Opinion, at present Copper stripped Wood Sheathing partly stripped  
as required by the Instructions, which had not been renewed in 1838 - bottom Caulked new  
false keel fitted new false Stern Post and Part new Rudder all  
new Stern Planks Counter and Coffer - two pair of Staple Bars  
fitted in two decks & windlass refitted with Patent Purchase  
Committee Minute 14th May 1845 Upper Caulked all over and bottom tested

Character assigned Fit for Service with Yellow Metal to the Wales - and  
Keel & Masts generally overhauled & in  
different Condition fit for the safe conveyance  
of dry & perishable Cargoes to & from all parts of the  
World and may be classed \*A with asterisk

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date 1845  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirketting _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks _____	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion,  
as required by the Instructions,

Committee Minute \_\_\_\_\_ 184

Character assigned \_\_\_\_\_



© 2019  
Lloyd's Register  
Foundation