

ANNUAL SURVEYS.

11585

No. 181 Survey held at London Date May 19 1845
 on the Bo. Effort Master J. Duff
 Tonnage 1160 Built at Yarmouth When built 1830
 By whom built _____ Owners Teasdale
 Port belonging to Yarmouth Destined Voyage Gibraltar
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1034 Port of London Continued 1845 Classed 4 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>Wet & found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Browsers 1 Stem 1 Wedge</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Main rigging new</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1040 good</u>

General Observations and Opinion, Appears in all respects in a good and efficient state
 as required by the Instructions, to retain her present class

Committee Minute 23rd May 1845

Character assigned 10 A 1

No. 338 Survey held at London Date May 19 & 20 1845
 on the Sr. Hiza & Jane Master Griffiths
 Tonnage 62 Built at Port Madoc When built 1839
 By whom built _____ Owners Griffiths & Co
 Port belonging to Beaumaris Destined Voyage Exeter
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 21 Port of Barmouth 1839 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>Wet & found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>2 Browsers 1 Stem 1 Wedge</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper _____

General Observations and Opinion, Painted in 1844 from the hull over all and is in good
 as required by the Instructions, condition to continue as classed

Committee Minute 23rd May 1845

Character assigned 10 A 1



Lloyd's Register
Foundation