

ANNUAL SURVEYS.

11592
Rd. H. May

No. 8 Survey held at London Date May 20 1845
on the Barge "Walker" Master J. Heay
Tonnage 326 Built at Sunderland When built 1839
By whom built 352 Owners Gateshead & Tyne Shipping Comp^y
Port belonging to Newcastle Destined Voyage
If Surveyed Afloat or in Dry Dock In Globe Dry Dock

Last Survey, No. 2300 Port of H'castle

Classed 9 A 1
5 Mo 44

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms	Capstan
Upper Deck Beams & Fastenings <u>d^o where seen</u>	Timbers of the Frame <u>good where seen</u>	Pumps
Lower Deck Beams & Fastenings <u>d^o</u>	Topsides <u>d^o</u>	Masts, Yards, &c. <u>in good condition and sufficient</u>
Spirkettling <u>d^o</u>	Wales <u>d^o</u>	Sails
Plank Shears <u>d^o</u>	Counter <u>d^o</u>	Cables
Waterways <u>d^o</u>	Plank and Treenails <u>d^o</u> (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings <u>d^o</u>	Rudder <u>refastened</u> <u>d^o</u>	Standing & Running Rigging
Breasthooks <u>d^o</u>	Windlass <u>d^o</u>	Copper <u>Felted 1844</u>

General Observations and Opinion,
as required by the Instructions,

The Don Hanging Knee, to Hold Beam which was broken now replaced. She appears in good condition and fit to remain as Class A 1

Committee Minute 23rd May 1845

Character assigned

9 A 1 J. A. Martin

No. 248 Survey held at London Date May 20 1845
on the Brig "Helen" Master Taylor
Tonnage 176 Built at Sunderland When built 1837
By whom built 191 Owners J. Balantine
Port belonging to Anstruther Destined Voyage Bahia
If Surveyed Afloat or in Dry Dock

Last Survey, No. 7667 Port of London

Classed 11 A 1
41

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms	Capstan
Upper Deck Beams & Fastenings <u>d^o where seen</u>	Timbers of the Frame <u>good where seen</u>	Pumps
Lower Deck Beams & Fastenings <u>d^o</u>	Topsides <u>d^o</u>	Masts, Yards, &c. <u>in good condition & sufficient</u>
Spirkettling <u>d^o</u>	Wales <u>d^o</u>	Sails
Plank Shears <u>d^o</u>	Counter <u>d^o</u>	Cables
Waterways <u>d^o</u>	Plank and Treenails <u>d^o</u> (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings <u>d^o</u>	Rudder <u>d^o</u>	Standing & Running Rigging
Breasthooks <u>d^o</u>	Windlass <u>d^o</u>	Copper <u>Yellow Metal now new</u>

General Observations and Opinion,
as required by the Instructions,

The Copper Sheathing stripp^d off the Bottom Caulked and re-sheathed with Yellow Metal upon Paper. She is in good condition and

Committee Minute 23rd May 1845

Character assigned

11 A 1 J. A. Martin
reced