

ANNUAL SURVEYS.

11098

No. 712 Survey held at London Date July 5th 1845
 on the Bh Medora Master P. Devere
 Tonnage 235 Built at Bristol When built 1825
 By whom built _____ Owners Curling, Young & Co
 Port belonging to London Destined Voyage Burice
 If Surveyed Afloat or in Dry Dock Afloat

Recd 10 July

Last Survey, No. 11012 Port of London Retained 1843 Classed 7 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging _____
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1841</u>

General Observations and Opinion, Presents a very firm & efficient state and may retain
 as required by the Instructions, her present class

W. M. D. M.

Committee Minute 11th July 1845

Character assigned Ret P 7 A 1

No. 207 Survey held at London Date July 5th 1845
 on the Ship Henry Master S. Dwyer
 Tonnage 201 Built at Leith When built 1833
 By whom built _____ Owners Curry & Co
 Port belonging to London Destined Voyage Burice
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11286 Port of London Continued 1843 Classed 3 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Buoys 1 Stm 2 Hedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1845</u>

General Observations and Opinion, Appears in all respects in a good & efficient condition
 as required by the Instructions, to continue in her present class

W. M. D. M.

Committee Minute 11th July 1845

Character assigned Ret P 3 A 1



© 2019

Lloyd's Register
Foundation