

ANNUAL SURVEYS.

11710

No. ²⁵⁴ Survey held at London Date July 1845
 on the Wh. Bottom Master _____
 Tonnage 541 Built at Liverpool When built 1822
 By whom built _____ Owners J. B. Radford
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 10792 Port of London Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Upper Deck Beams & Fastenings <u>Same</u>	Timbers of the Frame <u>do</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u> 184 <u>3</u>

General Observations and Opinion,
 as required by the Instructions,

Loaded and about taught for one found has
been recently overhauled is in an efficient condition for the
conveyance of dry and perishable cargoes to & from all parts of the
World and may remain as classed
 Committee Minute 15th July 1845
 Character assigned A, 1 Asst. Surveyor Hurdman

No. ¹⁰⁰ Survey held at London Date 5 July 1845
 on the Wh. Arie Master Smith
 Tonnage 116 Built at Rye When built 1840
 By whom built 28 Owners Temple
 Port belonging to Blackney Destined Voyage Kronenberg
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 6087 Port of Lpool Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Upper Deck Beams & Fastenings <u>Same</u>	Timbers of the Frame <u>do</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,
 as required by the Instructions,

He is in an efficient condition & may remain
as classed
 Committee Minute 15th July 1845
 Character assigned A, 1 Asst. Surveyor Hurdman



© 2019

Lloyd's Register
Foundation

LON619-0196