

ANNUAL SURVEYS.

11712

No. 24 Survey held at London Date May 27 to July 2nd 1845
 on the Rajasthan S Master P. Stewart
 Tonnage 601 Built at Bombay When built 1837
 By whom built _____ Owners Flemming & Co.
 Port belonging to Glasgow Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Wigram's Dock and E. & L. Docks

Last Survey, No. 9898 Port of London Classed 11 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good where seen</u>	Capstan <u>In good order</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good where seen</u>	Pumps <u>Lifted and examined</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>M and S have been out for repair.</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>2 Sails complete</u>
Plank Shears <u>"</u>	Counter <u>Good caulked</u>	Cables <u>250^{ft} & 3 large & good hawseers</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors <u>No. of 2 B & 1 D ordered 1 S. 2 K.</u>
Hatchway Comings <u>"</u>	Rudder <u>Examined - nothing</u>	Standing & Running Rigging <u>Refitted</u>
Breasthooks <u>"</u>	Windlass <u>Refitted</u>	Copper <u>Y. M. good being new over felt</u>

General Observations and Opinion, This ship has been stripped, hung in shores, keel seams caulked and the keel scarph
 as required by the Instructions, examined - and her bottom caulked and resheathed with Y. M. over felt
she is in good condition to remain as at present classed

Committee Minute 15th July 1845

Character assigned 11 A1 revised

Augustine Breuze
Hunting

No. 344 Survey held at London Date July 1st 1845
 on the London Bk Master Shuttleworth
 Tonnage 612 Built at London When built 1833
 By whom built _____ Owners Shuttleworth
 Port belonging to _____ Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock 2 D Docks

Last Survey, No. 11606 Port of London Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears <u>Good</u>	Counter	Cables
Waterways	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors <u>No. of</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>1843</u>

General Observations and Opinion, This ship has been lately reported since which her main hatch-ways
 as required by the Instructions, have been opened to receive machinery - by moving the hold beam
bodily forward & in and by making the upper deck beam to shift and be
set together again by screw bolts with nuts etc in a very efficient manner

Committee Minute 15th July 1845

Character assigned 12 A1 revised

Augustine Breuze
 Lloyd's Register
 Foundation