

ANNUAL SURVEYS.

11731
Recd 1845

No. 234 Survey held at London Date 5th July 1845
on the Bark Vulcan Master J. Patrick
Tonnage 263 Built at Dundee When built 1835
By whom built _____ Owners Patrick & Co
Port belonging to Dundee Destined Voyage St Petersburg
If Surveyed Afloat or in Dry Dock in Gun Dock

Last Survey, No. 733 Port of Dundee

Classed Y A 1 43

in 1843 Red 5 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>—</u>	Wales <u>—</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treenails <u>Worn and</u> (Outside to the Water's Edge.) <u>Pieces</u>	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Stripped off bottom</u>

General Observations and Opinion,
as required by the Instructions,

at present Copper stripped off bottom Cables Red
and grained to the bores. Copper not replaced
Several planks of the upper Courses particularly aft
on the larboard side were found worn and which
the Master was recommended to shift but
as he was pressed for time he made
for this present voyage them secure for the present by pieces and
has given an undertaking to renew the worn
planks on the ship's return. I consider
her in efficient condition for this voyage and
that for that time the ship remains as classed

Committee Minute

22nd July 1845

Character assigned

Rest 5

No. _____ Survey held at _____ Date _____ 1845

on the _____ Master J. A. Hutchie
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners Good Cause
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion,
as required by the Instructions,

Committee Minute _____ 184

Character assigned _____



© 2019

Lloyd's Register
Foundation