

# ANNUAL SURVEYS.

11791

No. 16 Survey held at London Date June 18<sup>th</sup> to Aug. 13 1845  
 on the Queen Master McLeod  
 Tonnage 1244 Built at Blackwall When built 1842  
 By whom built Green Wigram Green Owners Wigrams  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Wigram's Dock

Last Survey, No. 10910 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

|   |  |   |
|---|--|---|
| Decks <u>Main &amp; lower decks caulked</u> | Transoms <u>Good</u>   | Capstan <u>(South) good</u>                                       |
| Upper Deck Beams & Fastenings <u>Good</u>   | Timbers of the Frame <u>"</u>                                  | Pumps <u>Examined</u>   |
| Lower Deck Beams & Fastenings <u>Good</u>   | Topsides <u>"</u>  | Masts, Yards, &c. <u>Main fore &amp; mizzen out &amp; lead up</u> |
| Spirkettling <u>"</u>                       | Wales <u>"</u>   | Sails <u>2 Suits</u>  |
| Plank Shears <u>"</u>                       | Counter <u>"</u>   | Cables <u>8<sup>th</sup> &amp; 6<sup>th</sup> Hammer</u>          |
| Waterways <u>Cauked</u>                     | Plank and Treenails <u>"</u><br>(Outside to the Water's Edge.) | Anchors No. of <u>3 B. 1 S. 1 k.</u>                              |
| Hatchway Comings <u>Good</u>                | Rudder <u>Examined</u>   | Standing & Running Rigging <u>Overhauled</u><br>1844              |
| Breasthooks <u>"</u>                        | Windlass <u>Riding Butts good</u>                              | Copper <u>Y.M. Good</u>   |

General Observations and Opinion,  
as required by the Instructions,

*This ship has had her bottom examined in dry dock she is in good condition to remain as at present classed*

Committee Minute 15<sup>th</sup> Augt 1845

Character assigned 12 A 1

*Augustin Benez*  
*W. McLeod*

No. 404 Survey held at London Date August 11<sup>th</sup> 1845  
 on the Chieftain B<sup>2</sup> Master Walker  
 Tonnage 407 Built at Nova Scotia When built 1835  
 By whom built " Owners Thompson  
 Port belonging to London Destined Voyage Quebec  
 If Surveyed Afloat or in Dry Dock Pletcher's Dock

Last Survey, No. 11435 Port of Liverpool Classed 4 A.1

S.S. 45-342

The Surveyor is required to state the present Condition of the

|   |  |   |
|---|--|---|
| Decks <u>Good</u>                         | Transoms <u>Good when seen</u>                                 | Capstan <u>(small) in good order</u>  |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame <u>"</u>                                  | Pumps <u>"</u>  |
| Lower Deck Beams & Fastenings <u>"</u>    | Topsides <u>Good</u>   | Masts, Yards, &c. <u>"</u>  |
| Spirkettling <u>Good</u>                  | Wales <u>"</u>   | Sails <u>2 Suits one nearly new</u>   |
| Plank Shears <u>"</u>                     | Counter <u>"</u>   | Cables <u>3 B. Stream chain &amp; 2 good hawsers</u><br><u>Heavy stream</u> |
| Waterways <u>"</u>                        | Plank and Treenails <u>"</u><br>(Outside to the Water's Edge.) | Anchors No. of <u>3 B. 1 S. 1 kedge</u>                                     |
| Hatchway Comings <u>"</u>                 | Rudder <u>In good</u>  | Standing & Running Rigging <u>In good order</u>                             |
| Breasthooks <u>Good when seen</u>         | Windlass <u>In good order</u>                                  | Copper <u>Black bottom</u>  |


General Observations and Opinion,  
as required by the Instructions,

*The ship has been in dry dock to search for a leak - which it is supposed has been discovered and stopped - she is in good condition to remain as at present classed.*

Committee Minute 15<sup>th</sup> Augt 1845

Character assigned 4 A.1

*Augustin Benez*  
*W. McLeod*



©2019

Lloyd's Register  
Foundation