

ANNUAL SURVEYS.

11822

No. 73 Survey held at London Date August 25 1845
 on the Bg. Teresa Master James Low
 Tonnage 103 Built at Sunderland When built 1836
 By whom built _____ Owners Darlings & Co
 Port belonging to Stockholm Destined Voyage Stockholm
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10879 Port of London

Classed A, 1 Asterisk

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bows 3 Kedge</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>Patent</u>	Copper <u>stripped off in June last</u>

General Observations and Opinion, Copper stripped off, caulked, two pairs of additional iron
hanging knees to the side beams about 200 new treenails &
seven new planks on the decks, from a general good & sufficient
state we are of opinion she is fit for the safe conveyance of dry
& perishable cargoes and may retain her present class A, 1 Asterisk
26th August 1845.

Committee Minute

Character assigned A, 1 Asterisk

No. 308 Survey held at London Date August 25 1845
 on the Bk Cleopatra Master McDonchorn
 Tonnage 331 Built at Sunderland When built 1837
 By whom built _____ Owners Stirling & Co
 Port belonging to London Destined Voyage America
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 10508 Port of London

Classed IIA1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bows 1 Stm 2 Kedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>in 1842</u>

General Observations and Opinion, Is throughout in very efficient state and may retain
her present class

Committee Minute

Character assigned A, 1 Asterisk



© 2019

Lloyd's Register
Foundation