

ANNUAL SURVEYS.

11831

No. 706 Survey held at London Date August 15th 1845
 on the Lequette Master Crockford
 Tonnage 192 Built at Baitford When built 1839
 By whom built _____ Owners Crockford
 Port belonging to Limerick Destined Voyage Limerick
 If Surveyed Afloat or in Dry Dock on the Wages

Last Survey, No. 6075 Port of Sunderland Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound where seen</u>	Pumps
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c.
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper

General Observations and Opinion, Bottom examined & bolts caulked
 as required by the Instructions, From her general good & efficient appearance
may retain her present class

Committee Minute 29th Augth 1845

Character assigned 12 A 1

W. H. Dole
Surveyor

No. 158 Survey held at London Date August 20th 1845
 on the Ba Master Sanfesty
 Tonnage 126 Built at Guernsey When built 1838
 By whom built _____ Owners Cardiff & Co
 Port belonging to Guernsey Destined Voyage Genoa
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. _____ Port of Guernsey Classed 7A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>None</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound where seen</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>With found</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>2 Bowers 1 Skin 1 Hedge</u>
Hatchway Comings <u>"</u>	Rudder <u>new main piece</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>in 1842</u>

General Observations and Opinion, No symptoms of weakness or decay, and appears in
 as required by the Instructions, good condition to retain her present class

Committee Minute _____ 184

Character assigned _____

W. H. Dole

Surveyor