

# ANNUAL SURVEYS.

11832

No. <sup>30</sup> Survey held at London Date August 25 1845  
 on the Bk Queen of Britain Master Fitzgibbon  
 Tonnage 160 Built at Glocester When built 1830  
 By whom built Fitzgibbon Owners Fitzgibbon  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10722 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

|  |  |  |
|--|--|--|
| Decks <u>Good</u>                      | Transoms <u>Sound</u>                        | Capstan <u>Good</u>                    |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>Sound where seen</u> | Pumps <u>Good</u>                      |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u>                         | Masts, Yards, &c. <u>Well found</u>    |
| Spirkettling <u>"</u>                  | Wales <u>"</u>                               | Sails <u>Well found</u>                |
| Plank Shears <u>"</u>                  | Counter <u>"</u>                             | Cables <u>"</u>                        |
| Waterways <u>"</u>                     | Plank and Treenails <u>"</u>                 | Anchors No. of <u>"</u>                |
| Hatchway Comings <u>"</u>              | (Outside to the Water's Edge.) <u>"</u>      | Standing & Running Rigging <u>Good</u> |
| Breasthooks <u>"</u>                   | Rudder <u>"</u>                              | Copper <u>184.3</u>                    |
|  | Windlass <u>"</u>                            |  |

General Observations and Opinion, Caulked in May last from the Copper over all and is in a  
 as required by the Instructions, good condition to retain her present shape

Committee Minute 29<sup>th</sup> Aug 1845

Character assigned 12 A 1

No. 149 Survey held at London Date August 28 1845  
 on the Bk New Phoenix Master Baithen  
 Tonnage 362 Built at Hull When built 1813  
 By whom built F. Thomson Owners F. Thomson  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11126 Port of London Classed AE 1

The Surveyor is required to state the present Condition of the

|  |  |  |
|--|--|--|
| Decks <u>Good</u>                      | Transoms <u>Sound</u>                        | Capstan <u>Good</u>                          |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>Sound where seen</u> | Pumps <u>"</u>                               |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u>                         | Masts, Yards, &c. <u>Good</u>                |
| Spirkettling <u>Good</u>               | Wales <u>"</u>                               | Sails <u>well found</u>                      |
| Plank Shears <u>"</u>                  | Counter <u>"</u>                             | Cables <u>sufficient</u>                     |
| Waterways <u>"</u>                     | Plank and Treenails <u>Good</u>              | Anchors No. of <u>3 Bower 1 Stm 2 Hedges</u> |
| Hatchway Comings <u>"</u>              | (Outside to the Water's Edge.) <u>"</u>      | Standing & Running Rigging <u>Good</u>       |
| Breasthooks <u>"</u>                   | Rudder <u>"</u>                              | Copper <u>184.3</u>                          |
|  | Windlass <u>"</u>                            |  |

General Observations and Opinion, This vessel is in a good and efficient state for the safe  
 as required by the Instructions, conveyance of dry & perishable cargoes and may  
continue her present shape

Committee Minute 29<sup>th</sup> Aug 1845

Character assigned AE 1

