

# ANNUAL SURVEYS.

11848

No. 290 Survey held at London Date 30 Aug 1845  
 on the "Plymouth" Master Salembur  
 Tonnage 193 Built at Yarmouth When built 1834  
 By whom built — Owners Teigne & Co  
 Port belonging to London Destined Voyage Alger Bay  
 If Surveyed Afloat or in Dry Dock RC OK

Last Survey, No. 111.3 Port of London Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>as when seen</u>	Pumps <u>Good sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do do</u>
Spirkettling <u>do</u>	Wales <u>do</u>	Sails <u>do do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails <u>as</u> (Outside to the Water's Edge.)	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Plated upon copper 1845</u>

General Observations and Opinion,

as required by the Instructions, Is in Good sufficient Condition now Caulked from the Keel up and Sheathed to the Masts with yellow Metal to the Masts

Committee Minute 2nd Sept 1845

Character assigned 12 A1 1 recd of J. G.

No. 296 Survey held at London Date 30 August 1845  
 on the "The Belle" Master Brewer  
 Tonnage 283 Built at Shivers When built 1840  
 By whom built — Owners Horroby & Co  
 Port belonging to Wadebridge Plymouth Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 7299 Port of London Classed 7 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>2 suits</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>20 H. &amp; 20 W. &amp; 20 S.</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B 1 S 1 R</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Yellow Metal 1845</u>

General Observations and Opinion,

as required by the Instructions, Caulked from the Keel to the Masts and Sheathed with yellow Metal is in the most efficient

Committee Minute 2nd Sept 1845

Character assigned 7 A1 1 recd of J. G.