

ANNUAL SURVEYS.

11908
JP

No. 18 Survey held at London Date 16th Sept 1845
 on the "Bye Bee Wing" Master Smith
 Tonnage 163 Built at Hull When built 1828
 By whom built Gibson Owners E. Gibson
 Port belonging to Hull Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11248 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Same</u>	Timbers of the Frame <u>do when Sun</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do Sufficient</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper

General Observations and Opinion,

as required by the Instructions,

She appears in very good & efficient condition
fit for the conveyance of dry and perishable cargoes to & from
all parts of the world and may remain as Classed

Committee Minute 26th Sept 1845

Character assigned

Fit to service
LP

Fourteen

No. 187 Survey held at London Date 23 Sept 1845
 on the Blk Exporter Master
 Tonnage 216 Built at Redbridge When built 1825
 By whom built — Owners Royal
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11883 Port of London Classed Rest 8 A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Same</u>	Timbers of the Frame <u>do when Sun</u>	Pumps <u>Good Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>1844 Good</u>

General Observations and Opinion,

as required by the Instructions,

Is in the most efficient condition now
may remain as Classed

Committee Minute 26th Sept 1845

Character assigned

Rest 8 A.1
LP



© 2019

Lloyd's Register
Foundation