

ANNUAL SURVEYS.

11927
[Signature]
 602102

No. 392 Survey held at London Date Sept^r 3^d to Sept^r 26th 1845
 on the Windsor Master Prescott
 Tonnage 676 Built at London When built 1835
 By whom built Green Wigram Green. Owners R Green.
 Port belonging to London Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock East India Dock

Last Survey, No. 10925 Port of London Classed 1241

The present Condition of the

Decks <u>middle line work caulked</u>	Treenails <u>good</u>	Riding Bitts <u>Windlass</u> and Capstan <u>good New & piece to Biler</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>lifted</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>Long Boat & 2 Quarter Boats good</u>
Upper Deck Beams & Fastenings <u>good and</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>New & mark. In Mark new in India</u>
Lower Deck Beams & Fastenings <u>firm</u>	Keelsons <u>good</u>	Sails <u>2 sets and upwards</u>
Planksheers <u>caulked</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B 15 1k</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>210 fms</u>
Topsides <u>"</u>	Rudder <u>Examined in Dock</u>	Hawsers and Warps <u>9th New 7th good</u>
Wales <u>"</u>	Copper <u>Y. M. 1844 Rep^d</u>	Standing & Running Rigging <u>Overhauled</u>
Plank (Bottom) and Counter <u>caulked & above Copper</u>		

General Observations and Opinion, Yellow metal repaired and bottom examined in dry dock. Cask water & head repaired
Hawse pipes and Hawse rollers off to caulk head ends. Iron bobstay check kness rebolted. The
Ship is in an efficient state to remain as at present classed

Augustin Beuze

Committee Minute 7th Oct^r 1845

Character assigned 1241

Certificate (if required)

No. _____ Survey held at _____ Date _____ 184
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Committee Minute _____ 184

Character assigned _____

Certificate (if required)



© 2019

Lloyd's Register
 Foundation

LONG19-0419