

ANNUAL SURVEYS.

11929

No. 573 Survey held at London Date Oct 2nd 1845
 on the Ship 'Clifton' Master S. A. Cox
 Tonnage 897 Built at Bristol When built 1837
 By whom built 067 Owners De Tastet
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock In Mess^r Curling & Young's Dry Dock

Last Survey, No. 904 Port of Bristol Classed 10 A 1
44

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan
Waterways <u>d^o</u>	Breasthooks and Stemson	Pumps
Comings <u>d^o</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>d^o</u>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>d^o</u>	Keelsons <u>good</u>	Sails
Planksheers <u>d^o</u>	Clamps and Shelves	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling	Cables
Topsides <u>d^o</u>	Rudder	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>1044</u> <u>d^o</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,

This Ship is in good condition and eligible to remain as Class^o A 1

Committee Minute 24th Oct^r 1845
 Character assigned 10 A 1 Sa Martin
 Certificate (if required)

No. 153 Survey held at London Date Sept 27th 1845
 on the Ship 'Whampoa' Master J Willis
 Tonnage 340 Built at Sunduland When built 1841
 By whom built 376 Owners Willis & Co.
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Afloat in West India Dock

Last Survey, No. 11405 Port of London Classed 10 A 1

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan
Waterways <u>d^o</u>	Breasthooks and Stemson	Pumps
Comings <u>d^o</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats
Upper Deck Beams & Fastenings <u>d^o</u>	Timbers of the Frame <u>where seen</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>d^o</u>	Keelsons	Sails
Planksheers <u>d^o</u>	Clamps and Shelves	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>F&G M 42</u> <u>d^o</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>where seen d^o</u>		

General Observations and Opinion,

This is in good condition where seen and entitled to remain as Class^o A 1

Committee Minute 24th Oct^r 1845
 Character assigned 10 A 1 Sa Martin
 Certificate (if required)