

# ANNUAL SURVEYS.

1199  
77  
Dec 23 Cal.

No. 26 Survey held at London Date Oct 21 1845  
on the Ship "Savina" Master R. Mould  
Tonnage 327 Built at Shields When built 1841  
By whom built 404 Owners Mitcalp & Co  
Port belonging to S Shields Destined Voyage  
If Surveyed Afloat or in Dry Dock In Conson & Son's Shipway

Last Survey, No. 2382 Port of Hull Classed 10 A 1  
present Condition of the 44

Decks <u>good</u>	Treenails <u>good when seen</u>	Windlass and Capstan <u>good</u>
Stem <u>good</u>	Breasthooks and Stemson <u>good when seen</u>	Pumps <u>good</u>
Transoms, Pointers, and Crutches <u>seen</u>	Boats <u>good</u>	Masts, Yards, &c. <u>good</u>
Timbers of the Frame <u>seen</u>	Sails <u>good</u>	Keelsons <u>good</u>
Clamps and Shelves <u>good</u>	Anchors No. of <u>good</u>	Clamps and Shelves <u>good</u>
Ceiling <u>good</u>	Cables <u>good</u>	Ceiling <u>good</u>
Rudder <u>good</u>	Hausers and Warps <u>good</u>	Rudder <u>good</u>
Copper <u>good</u>	Standing & Running Rigging <u>good</u>	Copper <u>good</u>

*In good condition and sufficient*

General Observations and Opinion, This ship appears in good condition and fit to remain as Class 10 A 1

Committee Minute 28th Oct 1845  
Character assigned 10 A 1  
Certificate (if required) Ja Martin

No. 880 Survey held at London Date Oct 22 1845  
on the Ship "Columbus" Master C Short  
Tonnage 407 Built at Whitley When built 1832  
By whom built London Owners Fletcher  
Port belonging to London Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock In Fletcher's Dry Dock

Last Survey, No. 1688 Port of London Classed 11 A 1  
present Condition of the Cont 45. 4. 44

Decks <u>good</u>	Treenails <u>good when seen</u>	Windlass and Capstan <u>good</u>
Waterways <u>good</u>	Breasthooks and Stemson <u>good when seen</u>	Pumps <u>good</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>seen</u>	Boats <u>good</u>
Upper Deck Beams & Fastenings <u>seen</u>	Timbers of the Frame <u>seen</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>seen</u>	Keelsons <u>good</u>	Sails <u>good</u>
Planks/Decks <u>good</u>	Clamps and Shelves <u>good</u>	Anchors No. of <u>good</u>
Sheerstrakes <u>good</u>	Ceiling <u>good</u>	Cables <u>good</u>
Topsides <u>good</u>	Rudder <u>good</u>	Hausers and Warps <u>good</u>
Wales <u>good</u>	Copper <u>good</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

*In good condition and sufficient*

General Observations and Opinion, The Yellow Metal Sheathing now stripped off the ship hung, Bottom Caulked and re-sheathed with Yellow Metal. She is in good condition

Committee Minute 28th Oct 1845  
Character assigned 11 A 1  
Certificate (if required) Ja Martin

LON 620-0029