

# ANNUAL SURVEYS.

12086

No. 357 Survey held at London Date Nov 11/12 22 1845  
 on the Mr. London Master Hinson  
 Tonnage 388 Built at Calcutta When built 1825  
 By whom built — Owners Boyer  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Afloat

Dec 27/45

Last Survey, No. 11027 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Affluent</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>to Water Line</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>—</u>
Spirketting <u>Good</u>	Wales <u>—</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treennails <u>—</u> (Outside to the Water's Edge)	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Good</u>

General Observations and Opinion, Two brass pointers now put in at my suggestion  
 as required by the Instructions, and the apparatus good and substantial fit for the  
conveyance of dry & perishable cargo to & from all parts

Committee Minute 20th Nov 1845 of the World & my command

Character assigned A.1 Attending Captain Plowteney  
Special

No. 250 Survey held at London Date Nov 15 2 1845  
 on the Whitburn Duke Master R. Mervin  
 Tonnage 126 Built at Exmouth When built 1840  
 By whom built — Owners Clay & Co.  
 Port belonging to London Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11723 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>—</u>	Pumps <u>Affluent</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>—</u>
Spirketting <u>Good</u>	Wales <u>—</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treennails <u>—</u> (Outside to the Water's Edge)	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Good</u>

General Observations and Opinion, She is in the best efficient condition  
 as required by the Instructions, and may remain so Classed

Committee Minute 20th Nov 1845

Character assigned 12A1

Lloyd's Register  
 Foundation

LN620-CT20