

REPORT of SURVEY for REPAIRS.

12094

Change of Owners

No. 720 Survey held at Sunder Date Nov 29th to Dec 3rd 1845
 on the Bk Arachne Master Moxey
 Tonnage 314 Built at Doverport When built 1809
 By whom built _____ Owners J. Senterfle
 Port belonging to Sunder Destined Voyage Amey
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 10171 1843 Classed A, 1 Asterisk
expunged
 Port of Sunder

REPAIRS Bottom shipped and caulked, several of the hold beam fastenings removed in the shock of the waves which had been removed by the copper, the outside planking warped tight and several beenailed down out which are in good condition as well as the planks through which they pass.
 Sheathed with yellow Metal or felt.

Present Condition of the

Docks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stelson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & new</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelson <u>good</u>	Sails <u>red & hand</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	<u>yellow Metal</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion. We are of opinion from her good & efficient state she is fit for the safe conveyance of cargo & passengers to & from all parts of the world and may be classed A, 1 Asterisk

The Amount of Fee £ 2 is received by me,

Certificate (if required) : 10 :-

Committee's Minute 5th Dec 1845

Character assigned A, 1 asterisk

LON 620-0128