

ANNUAL SURVEYS.

12111

No. 16 Survey held at Sonia Date 11th 29th Dec 1845
 on the Br Carl Master J Burman
 Tonnage 143 Built at Sulia When built 1835
 By whom built _____ Owners Bezman
 Port belonging to Sulia Destined Voyage Cissa
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 247 Port of Wrotte Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>None</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>None</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Not used</u>
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treennails (Outside to the Water's Edge) _____	Anchors No. of <u>3 Buoys 1 Gun 1 Rig</u>
Hatchway Coverings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
Breasthooks _____	Windlass _____	<u>Shroth the with iron bands</u>

General Observations and Opinion, In 1845 I examined the sheathing with iron bands over the
 as required by the Instructions, at the present time one pair of iron hanging rings and one pair of the
into beams to compensate for a broken loggins screw, in
general good condition I am of opinion she is fit for the safe
carriage of any perishable cargoes and may retain her
present shape Dec 11th 1845 Wrotte

Committee Minute _____

Character assigned _____

No. 188 Survey held at Sonia Date Dec 6th 184
 on the Br Cybele Master Guffeth
 Tonnage 334 Built at Perimutli When built 1841
 By whom built _____ Owners Colling & Co
 Port belonging to Sonder Destined Voyage Barbice
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11539 Port of Sonia Classed SA1

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables _____
Waterways _____	Plank and Treennails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Coverings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion, Bottom examined of the throughout is in a very efficient
 as required by the Instructions, state and may retain her present shape

Committee Minute _____

Character assigned _____

Lloyd's Register
Foundation

LON 620-0145