

REPORT of SURVEY for REPAIRS.

Change of Owners

12162

No. 137 Survey held at London Date November 1845
 on the Bk Caroline Master W. Stone
 Tonnage 344 Built at London When built 1811
 By whom built Higgin & Green Owners W. Stone & Marlam & Co.
 Port belonging to South Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11520 Classified 12 A1

Port London

REPAIRS Caulked from the Copper to the gunwale

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>45</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Ship in all respects in a very efficient state to continue in her present service

The Amount of Fee.....£ 2 is received by me, W. Stone

Certificate (if required)

Committee's Minute 12 Aug 1845

Character assigned 12 A1

© 2015

Lloyd's Register Foundation

LON 620-0197