

# ANNUAL SURVEYS.

No. 568 Survey held at Lندن Date Feb'y 9<sup>th</sup> 1846  
 on the Ship Emerald Isle Master Cutler  
 Tonnage 581 Built at Shoolmain When built 1836  
 By whom built \_\_\_\_\_ Owners E. Ford  
 Port belonging to Lندن Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Higams Dock

Last Survey, No. 10929 Port of Lندن

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound &amp; secure</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Not fair</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper <u>"</u>
	Windlass <u>"</u>	

General Observations and Opinion, Caulked from the upper to the waterway seam and  
 as required by the Instructions, is in all respects in good & efficient state to retain  
her present character

Committee Minute 24th July 1846

Character assigned 12A1

No. \_\_\_\_\_ Survey held at Londen Date Feb'y 16<sup>th</sup> 1846  
 on the Ship Perriek Hall Master Briggett  
 Tonnage 345 Built at Farmouth When built 1837  
 By whom built \_\_\_\_\_ Owners Briggett & Co.  
 Port belonging to Londen Destined Voyage W. India  
 If Surveyed Afloat or in Dry Dock Dorsons Dry Dock

Last Survey, No. \_\_\_\_\_ Port of Londen

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound &amp; secure</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables _____
Waterways <u>"</u>	Plank and Treennails <u>"</u>	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper _____
	Windlass _____	

General Observations and Opinion, Bottom caulked & sheathed with yellow metal  
 as required by the Instructions, over paper and is in all respects in a good & efficient  
state to retain her present shape

Committee Minute 184

Character assigned \_\_\_\_\_

LON 620-0321