

# ANNUAL SURVEYS.

12306  
H  
Dec 17 1844

No. 136 Survey held at London Date March 16 1846  
 on the "Nelson" Master W H Lamond  
 Tonnage 510 Built at Dumbarton When built 1844  
 By whom built 603 Owners Potter & Co  
 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock In possession of Young's Dry Dock

Last Survey, No. 1169 Port of London Classed 10 A 1  
3<sup>rd</sup> cl<sup>ss</sup>

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan
Waterways <u>d<sup>o</sup></u>	Breasthooks and Stenson	Pumps
Comings <u>d<sup>o</sup></u>	Transoms, Pointers, and Crutches <u>good when seen</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings <u>d<sup>o</sup></u>	Keelsons <u>d<sup>o</sup></u>	Sails <u>and sufficient</u>
Planksheers	Clamps and Shelves <u>d<sup>o</sup></u>	Anchors No. of
Shoestrakes <u>d<sup>o</sup></u>	Ceiling <u>d<sup>o</sup></u>	Cables
Top-sides <u>d<sup>o</sup></u>	Rudder <u>d<sup>o</sup></u>	Hawsers and Warps
Wales <u>d<sup>o</sup></u>	Copper <u>Soft Metal 44 d<sup>o</sup></u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d<sup>o</sup></u>		

General Observations and Opinion, Now done, about 2 doz sheets of Yellow Metal expended in Patching Bottom; the Ship caulked outside. She is in good condition fit to remain as Class. A 1

Committee Minute 20th Mar 1846 J. Martin  
 Character assigned 10 A 1 W. H. Lamond  
Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 184 \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_


Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails	Windlass and Capstan
Waterways _____	Breasthooks and Stenson	Pumps
Comings _____	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers _____	Clamps and Shelves	Anchors No. of
Shoestrakes _____	Ceiling	Cables
Top-sides _____	Rudder	Hawsers and Warps
Wales _____	Copper	Standing & Running Rigging
Plank (Bottom) and Counter _____		

General Observations and Opinion, \_\_\_\_\_

Committee Minute \_\_\_\_\_ 184 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
Certificate (if required)



© 2019

Lloyd's Register  
 Foundation

LON 620-0395