

# ANNUAL SURVEYS.

12386

No. 373 Survey held at London Date March 20 1846  
 on the Ship Duke of Cornwall Master J. Whitehead  
 Tonnage 575 Built at Bristol When built 1843  
 By whom built J. Eyles Owners J. Eyles  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock East India Dock

6224/1000

Last Survey, No. 11409 Port of London 1045 Classed 12 A1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound &amp; true</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shells <u>"</u>	Anchor No. of 3 Bower 1 Star 2 Bigger
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>sufficient</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>LS</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Bottom examined in dry dock and caulked from the upper to the garboard  
in place of iron hanging diagonal knees to the aft end of the beam, new  
iron net and the rigging overhauled and appears in all respects  
in good & efficient state to return her present cargo

Committee Minute 31 March 1846  
 Character assigned 12 A1 L.P.  
 Certificate (if required) Aug. Bruze

No. 373 Survey held at London Date March 15 1846  
 on the Ship William Sharp Master McLennan  
 Tonnage 432 Built at Glasgow When built 1839  
 By whom built Shaggle Owners Shaggle  
 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Burton & Youngs Dock

Last Survey, No. 11315 Port of London Classed 10 A1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>sound</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound &amp; true</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shells <u>"</u>	Anchor No. of 3 Bower 1 Star 2 Bigger
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>sufficient</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, has plank on the deck next the waterway 4 pair of a Dubaut  
hanging waterway to the deck beam, ceiling well up  
and general overhaul and from her general good condition  
made conformable to class

Committee Minute 31 March 1846  
 Character assigned 10 A1 L.P.  
 Certificate (if required) Aug. Bruze