

Change of Owners 12608

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date May 25th 1846
on the Ship "Udelaide" Master Wharton
Tonnage 640 Built at Calcutta When built 1832
By whom built _____ Owners J & F Somers
Port belonging to London Destined Voyage Hobart Town
If Surveyed Afloat or in Dry Dock In Fletcher's Dry Dock, afloat at Deptford

Last Survey, No. _____ Classed 12 A1
Port _____ Cont 46 . 4 4m045

REPAIRS now done . The Ship Dock^d to examine Bottom, about 4 sheets of yellow metal expended in Patching, all the rest good. Caulked from Y metal upwards.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Ship appears in good condition throughout and is entitled to remain as Class A1

The Amount of Fee £ : : is received by me, J A Martin
Certificate (if required) : :

Committee's Minute _____ 18

Character assigned _____