

REPORT of SURVEY for REPAIRS.

1261

No. ✓ Survey held at London Date June 23 1846
 on the "Hermi City of Hamburg" Master ✓
 Tonnage 379 Built at London When built 1834
 By whom built Navies Owners G. S. H. Co.
 Port belonging to London Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 9910 Classed 12 A1
 Port London

REPAIRS 1845 docked stripped bottom caulked and
 ushered with copper sheet diagonal keelings
 put in and the vessel generally overhauled
New Boilers 1845
The Engine appears in good condition

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper ed 1845 / September	Standing & Running Rigging

General Observations and Opinion, The appears sound and fastenings
seems to be in an efficient condition and may
remain as shipped

The Amount of Fee.....£ : : is received by me.

Certificate (if required) : :

Committee's Minute 26th June 1846

Character assigned 12 A1 Upd



© 2019

Lloyd's Register
Foundation

LON 621-0161