

ANNUAL SURVEYS.

12645

No. 248 Survey held at London Date July 8th 1846
 on the Bg. Menez Master J. B. Light
 Tonnage 154 Built at Swanland When built 1839
 By whom built _____ Owners Forster & Co.
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock London Dock

Recd July 14

Last Survey, No. 10751 Port of London

Classed 10A1

The present Condition of the

Decks	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Brooms 1st 1 1/2 dge</u>
Sheerstrakes	Ceiling <u>"</u>	Cables <u>sufficient</u>
Topsides	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales	Copper <u>all</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion, I have been on the way, bottom examined & caulked above the copper, and is in all respects in good condition to continue in her present class

Committee Minute 10th July 1846

Character assigned 10A1

W. M. Lister

Certificate (if required)

No. 582 Survey held at London Date July 8th 1846
 on the Mr. Sprightly Master W. R. Smith
 Tonnage 145 Built at Hull When built 1845
 By whom built _____ Owners Smith & Co.
 Port belonging to London Destined Voyage Amsterdam
 If Surveyed Afloat or in Dry Dock Afloat

W. M. Lister

Last Survey, No. 12193 Port of London

Classed 0A1

The present Condition of the

Decks	Treenails	Windlass and Sam <u>winch</u> <u>good</u>
Waterways	Breasthooks and Stemson	Pumps <u>"</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>two</u> <u>"</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>well found</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>"</u>
Sheerstrakes	Ceiling	Cables <u>"</u>
Topsides	Rudder	Hawsers and Warps <u>"</u>
Wales		Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion, A broken hold beam replaced, and is now in a very good & efficient state to retain her present class

Committee Minute 10th July 1846

Character assigned 0A1

W. M. Lister

Certificate (if required)