

ANNUAL SURVEYS.

12649

No. 175 Survey held at London Date June 25th 1846
 on the Bk Diamond Master Taylor
 Tonnage 573 Built at Sole of Man When built 1835
 By whom built _____ Owners Admiral
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Union Dock

Last Survey, No. 11639 Port of London 1045 Classed E, 1st Risk

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>three</u>
Upper Deck Beams & Fastenings <u>good firm</u>	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bows 1 Stem 2 Hedges</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>sufficient</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>good</u>
Wales <u>"</u>	Copper <u>44</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Bottom examined, and appears in all respects in a good & efficient state for the safe conveyance of dry & perishable cargo to & from all parts of the world and may continue as classed E, 1st Risk

Committee Minute 10th July 1846

Character assigned E, 1st Risk

Certificate (if required)

No. 376 Survey held at London Date June 30th 1846
 on the Ship True Briton Master Condit
 Tonnage 606 Built at London When built 1835
 By whom built _____ Owners Wigram &
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11051 Port of London Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>well found</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>44</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Topsides & waterways caulked, under unhang & upper braces fitted, and in good condition to retain her present class

Committee Minute 10th July 1846

Character assigned 12A1

Certificate (if required)