

ANNUAL SURVEYS.

12657

No. 126 Survey held at London Date 26 July 1846
 on the "H.M. Sab" Master Summers
 Tonnage 415 Built at Stockton When built 1840
 By whom built _____ Owners Living
 Port belonging to Bristol Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock afloat had been in dry dock

Re: 27 July

Last Survey, No. 11481 Port of London Classed 8A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B & 1 K</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion, Had been over hauled in Mr. T. Barlings Dock
 as required by the Instructions, is in an efficient condition and may remain as
Classed -

Committee Minute 10th July 1846
 Character assigned 8A1

No. 297 Survey held at London Date June 28 1846
 on the "H.M. Rob Roy" Master W. J.borough
 Tonnage 178 Built at Aberdeen When built 1841
 By whom built _____ Owners W. J.borough
 Port belonging to Dutch Destined Voyage North
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 12570 Port of London Classed 6A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>Good</u>	Sails <u>do</u>
Plank Shears _____	Counter _____	Cables <u>do</u>
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>do</u>
Breasthooks _____	Windlass _____	Copper <u>do</u>

General Observations and Opinion, Is in a good condition and may
 as required by the Instructions, remain as Classed

Committee Minute 10th July 1846
 Character assigned 6A1