

REPORT of SURVEY for REPAIRS.

No. 304 Survey held at London Date July 8th 1846
on the MS "Juscan" Master Robson
Tonnage 184 Built at Poole When built 1831
By whom built — Owners Jarguhorson
Port belonging to London Destined Voyage —
If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 11560

Classed 600 4 A 1
Cert. 1842

Port London

REPAIRS

MS Shipped bottom baulked and sheathed
with yellow metal, and some additional knees to
Deck Beams, and has been generally over hauled

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

She appears in a very sound & efficient
Condition and in my opinion entitled to have the
full period of Continuation say 4 A 1 from 1843

The Amount of Fee.....£ 2 : 2 : — is received by me, H. Courtney

Certificate (if required) : :

Committee's Minute 24 July 1846

Character assigned Cert. 4 A 1 1843

Wm. H. H. H.
Leslie H. H.



© 2019

Lloyd's Register
Foundation

LON 621-0232