

12701 *Jon*
 Her Masts, Yards, &c. are in good condition, and sufficient in size and length. *of Teak*

She has SAILS.		CABLES, &c.		ANCHORS, and their weights.	
N ^o .		Fathoms.		Inches.	N ^o .
2	Fore Sails,	200	Chain		3
2	Fore Top Sails,		Hempen Stream Cable <i>none</i>		
2	Fore Topmast Stay Sails,		Hawser <i>... Cold</i>	7	Bower, & <i>... Sufficient</i>
2	Main Sails,		Towlines <i>... da</i>	6	Stream,
3	Main Top Sails,		Warp		Kedge,
and <i>au loon</i>			All of		
			quality.		

Her Standing and Running Rigging of good sufficient in size and good in quality.

She has One Long Boat and two others

The present state of the Windlass is - Capstan good and Rudder good

General Remarks—Statement and Date of Repairs.

Listings had been cut out to afford an inspection of the frame according to the Society's Rules, the materials appear to be of the best description

An additional Breast Hook put in and now bolted through the Keelson at every floor and the sheels also additionally bolted 2 stops *down* and one pair *M.H.* to upper deck added, at Surveyors suggestion

I recommended that 7 pairs of iron hanging knees, ^{or standards} should be put to the lower deck Beams their being no knees whatever to the four after most Beams, and the distance between those Beams that has knees being $8-7-9-3-10-0-7-0-10-2$

I am of opinion that she requires of further security in respect of the lower deck Beams— but the ^{with wood} *power* declines to put them in, left to Committee

If Sheathed, ~~Doubled~~, Felted, or Coppered Yellow Paint 1845 When last done to decide upon

I am of opinion this Vessel should be Classed _____

The Matter

The Amount of the Fee.....£ 5 : - : — is received by me, *AS*

Special£ : :

Certificate (if required)£ : :

How ten

Committee's Minute 30 July 1846

Character assigned Classey registered to the port

Classey registered to the port

but can't be put into the

Classey registered to the port



© 2019 Lloyd's Register Foundation

under given in report
to the committee