

REPORT of SURVEY for REPAIRS.

No. 49 Survey held at London Date June 13 to July 14 1846
 on the Bth Carl Grey Master
 Tonnage 571 Built at Newcastle When built 1835
 By whom built _____ Owners Messrs Dunbar & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In the East India Dock

Last Survey, No. 12180 Classed 10 A 1
 Port London Cont 45.3 45

REPAIRS at present

The Upper Deck Doubled with Plywood for
 inches thick upon Felt. The Yellow Metal Sheathing
 stripped off, the Ship Caulked throughout and the Bottom
 resheathed with Yellow Metal upon Felt; Ship hung in
 Shores and Keel Seam Caulked

Present Condition of the

Upper Deck Beams & Fastenings	good when seen	Treenails	_____	Windlass and Capstan	_____
Lower Deck Beams & Fastenings	d ^o	Breasthooks and Stemson	_____	Pumps	_____
Planksheers	d ^o	Transoms, Pointers, and Crutches	good when seen	Boats	_____
Keelstrakes	d ^o	Timbers of the Frame	_____	Masts, Yards, &c.	In good order
Topsides	d ^o	Keelsons	d ^o	Sails	and sufficient
Wales	d ^o	Clamps and Shelves	d ^o	Anchors No. of	_____
Plank (Bottom) and Counter	d ^o	Ceiling	d ^o	Cables	_____
		Rudder	d ^o	Hawsers and Warps	_____
		Copper	Yellow Metal now upon Felt	Standing & Running Rigging	_____

General Observations and Opinion,

This Ship is in good condition throughout
 and entitled to remain as Classed. A 1

The Amount of Fee.....£ : : is received by me,

Certificate (if required) : :

Committee's Minute 13 Aug 1846

Inspector assigned Comd 3rd A 1 - recd



© 2019

Lloyd's Register
 Foundation
 LON 621 0277