

ANNUAL SURVEYS.

12909

No. 99 Survey held at London Date Feb 15th 1843
 on the Ship "Castle Eden" Master
 Tonnage Built at Switzerland When built 1842
 By whom built Mason & Owners
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Miss Collins & James

Original Survey, No. Port of Classed

The Surveyor is required to state the present Condition of the


Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u> </u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u> </u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good &</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>well found</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u> </u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>of Mr 1042</u>

General Observations and Opinion,
 as required by the Instructions,

The good build & well fastened Ship well
entitled to all the Rules will allow her

Committee Minute 184

Character assigned



© 2019

Lloyd's Register
 Foundation

LON 621-0470