

ANNUAL SURVEYS.

12995
H
Recd 26 Nov

No. 514 Survey held at London Date 31st Oct 1846
on the BK "Ellen" Master Grathwaite
Tonnage 409 Built at Sheff Man When built 1836
By whom built Owners R Battersby
Port belonging to Liverpool Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock in Lime Kiln Dock

Last Survey, No. 7141 Port of Liverpool Classed *A. 1

The present Condition of the

Decks <u>Caulked Good</u>	Treenails <u>Holden</u>	Windlass and Capstan <u>Good</u>
Waterways <u> </u>	Breasthooks and Stemson <u>Good</u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u>Three</u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u>New Fore & Main Masts</u>
Lower Deck Beams & Fastenings <u> </u>	Keelsons <u> </u>	Sails <u>Sufficient</u>
Planksheers <u> </u>	Clamps and Shelves <u> </u>	Anchors No. of <u>3 B 1 S 1 K</u>
Sheerstrakes <u> </u>	Ceiling <u> </u>	Cables <u>Suff</u>
Upsides <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Wales <u> </u>	Copper <u>Ym 45 good</u>	Standing & Running Rigging <u>New backstays & Shifting in good</u>
Plank (Bottom) and Counter <u> </u>		

General Observations and Opinion,

This vessel appears in very efficient condition and my opinion may remain

Committee Minute 1st Dec 1846 Claped *A. 1 with detent
Character assigned 10 A 1 Reports

Certificate (if required)

No. 21 Survey held at London Date 6 Nov 1846
on the BK "Queen" Master
Tonnage 385 Built at Dumbarton When built 1844
By whom built Owners Martin & Co
Port belonging to Greenock Destined Voyage
If Surveyed Afloat or in Dry Dock in Curling Young & Co Dock

Last Survey, No. 12951 Port of London Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Planksheers <u> </u>	Clamps and Shelves <u> </u>	Anchors No. of <u> </u>
Sheerstrakes <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Upsides <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Wales <u> </u>	Copper <u>Ym on Paper</u>	Standing & Running Rigging <u> </u>
Plank (Bottom) and Counter <u> </u>		

General Observations and Opinion,

at present bottom stripped Caulked and sheathed with Y metal on Paper. New lacing to head and stern of head additionally bolted

Committee Minute 1st Dec 1846 appears in very efficient condition
Character assigned 10 A 1 and my Certificate assigned

Certificate (if required)