

# ANNUAL SURVEYS.

13032

No.        Survey held at London Date 15 Nov 8 1846  
 on the B. Susannah Master A Campbell  
 Tonnage 444 Built at Nylton When built 1844  
 By whom built        Owners Campbell &  
 Port belonging to London Destined Voyage         
 If Surveyed Afloat or in Dry Dock in Mr Tindalls Dock

Last Survey, No.        Port of        Classed       

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Copsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

At Present from Damage bottom stripped hung  
 Caulked and Resheathed with Metal on Paper  
 and Damage to bulwarks repaired - is in very  
 efficient Condition and may  
 remain as Clapnet

Committee Minute        1846

Character assigned       

Special damage £

Certificate (if required)

No. 933 Survey held at London Date 28 Nov & Dec 1846  
 on the Ship "Australia" Master Harrison  
 Tonnage 343 Built at        When built 1826  
 By whom built        Owners English  
 Port belonging to Liverpool Destined Voyage Cape G Hope & Ceylon  
 If Surveyed Afloat or in Dry Dock in Fitchers Dock

Last Survey, No. 7061 Port of Liverpool Classed 10 A 1  
1842 Red 7 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Copsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

at Present a Pair of long Run Keels fitted in after  
 body full both beam Clamped (in photo) and an additional pair of  
 hanging iron Keels fitted to it several wood lodging Keels of hold beams  
 rebolted opened for Government Survey hunters found sound

Committee Minute 22 Dec 1846

Character assigned       

Certificate (if required)