

ANNUAL SURVEYS.

13172

No. 435 Survey held at London Date 29 Jan 1847
 on the John Nuttall Master Christopher
 Tonnage 284 Built at Sunderland When built 1841
 By whom built _____ Owners Blyth & Green
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Curling's Dock

Last Survey, No. 10464 Port of London Classed 9A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>	Pumps <u>new belye pump</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>three</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Masts, Yards, &c. <u>new fore & main mast out & foremast others sufficient</u>
Lower Deck Beams & Fastenings <u>—</u>	Keelsons <u>—</u>	Sails <u>—</u>
Planksheers <u>Caulked Good</u>	Clamps and Shells <u>—</u>	Anchors No. of <u>3 @ 1.10</u>
Sheerstrakes <u>—</u>	Ceiling <u>—</u>	Cables <u>sufficient</u>
Topsides <u>—</u>	Rudder <u>—</u>	Hawsers and Warps <u>—</u>
Wales <u>Caulked Good</u>	Plank (Bottom) and Counter <u>—</u>	Standing & Running Rigging <u>—</u>

General Observations and Opinion,

at present bottom stripped Caulked and Sheathed
 with Yellow Metal part on felt part on paper
 has been generally overhauled & is efficient

Committee Minute 19th Feb 1847 Condition and may continue as
 Character assigned clapd by St. R. Kitchie
10 A 1 Good Ms

Certificate (if required)

No. 346 Survey held at London Date 27 Jan 1847
 on the Greenlaw Master W. Owen
 Tonnage 406 Built at Montrose When built 1839
 By whom built _____ Owners Ar. K. Coll & Farncomb
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Wigram's Dock

Last Survey, No. 12013 Port of London Classed 10A1

The present Condition of the

Decks <u>Caulked Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>	Pumps <u>—</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>—</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Masts, Yards, &c. <u>sufficient</u>
Lower Deck Beams & Fastenings <u>—</u>	Keelsons <u>—</u>	Sails <u>—</u>
Planksheers <u>—</u>	Clamps and Shells <u>—</u>	Anchors No. of <u>—</u>
Sheerstrakes <u>Caulked</u>	Ceiling <u>—</u>	Cables <u>—</u>
Topsides <u>—</u>	Rudder <u>—</u>	Hawsers and Warps <u>—</u>
Wales <u>—</u>	Plank (Bottom) and Counter <u>—</u>	Standing & Running Rigging <u>—</u>

General Observations and Opinion,

This Vessel appears in efficient Condition
 and may continue as Clapd

Committee Minute 19th Feb 1847
 Character assigned 10 A 1 Good Ms
St. R. Kitchie

© 2019

Lloyd's Register
 Foundation

Certificate (if required)