

ANNUAL SURVEYS.

1318

No. 13 Survey held at London Date Jan 30 1847
 on the Sh. "Cambria" Master Sheddicks
 Tonnage 347 Built at Milford When built 1838
 By whom built 449 Owners Rader & Co.
 Port belonging to Milford Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock, L. & A. & Co.

Last Survey, No. 312 Port of Milford Classed 12 A

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 13</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter		

General Observations and Opinion, The new Wood Beam new plank of the deck
and the waterway part new plank also on the starboard
side bottom caulked and sheathed with yellow lead

Committee Minute 26th Feb 1847 is in good and efficient condition
 Character assigned 12 A and may remain as classed

Certificate (if required)

No. 537 Survey held at London Date Feb 9 1847
 on the Sh. "Sovereign" Master Shewell
 Tonnage 223 Built at Dumbarton When built 1834
 By whom built — Owners Campbell
 Port belonging to Glasgow Destined Voyage T
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1977 Port of Glasgow Classed 11 A

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>—</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>—</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, She appears in good efficient condition
and may remain as classed

Committee Minute 26th Feb 1847

Character assigned 11 A



© 2019

Lloyd's Register
Foundation