

ANNUAL SURVEYS.

13232

No. 52 Survey held at London Date March 11th 1847
 on the James Duncan Master England
 Tonnage 208 Built at Belgum When built 1839
 By whom built 2nd Owners England
 Port belonging to London Destined Voyage West India & Africa
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 12362 Port of London Classed SA1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>sound</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>1/2 in 45</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, The hull and topsides scraped and painted sound and good is in an efficient condition and may remain as classed

Committee Minute 17th March 1847
 Character assigned SA1

Certificate (if required)

No. 123 Survey held at London Date March 11. 16. 1847
 on the Tris Master
 Tonnage 248 Built at Jersey When built 1838
 By whom built Owners Wilcox
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 7493 Port of Liverpool Classed Gen SA

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>sound</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>new caps</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>good</u>	Sails <u>do</u>
Planksheers <u>good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>1/2 in 45</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, She is in an efficient condition and may remain as classed

Committee Minute 17th March 1847
 Character assigned Gen SA

© 2019
 Lloyd's Register
 Foundation
 Certificate (if required)