

ANNUAL SURVEYS.

13321

No. 151 Survey held at London Date April 14 1847
 on the Ag. Agamemnon Master Proctor
 Tonnage 283 Built at Sunderland When built 1839
 By whom built 294 Owners Hick & Co
 Port belonging to Scarbro Destined Voyage Gibraltar
 If Surveyed Afloat or in Dry Dock afloat and been on the New Cross Ways

Last Survey, No. 1391 Port of Hull Classed 9A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good when seen</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Seems</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 15 1 K</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>efficient</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>4th 45</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, She is good and efficient condition and may remain as classed
H. J. Porter

Committee Minute 23rd April 1847

Character assigned 9A1

Certificate (if required)

No. 169 Survey held at London Date April 19 1847
 on the Thomas Blyth Master J. Thompson
 Tonnage 372 Built at Sydney When built 1837
 By whom built do Owners Blyth & Co
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Dry Dock / Laverney

Last Survey, No. 1207 Port of London Classed 10A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Seems</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 15 1 K</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>4th 45</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Is in good & efficient condition and may remain as classed
H. J. Porter

Committee Minute 23rd April 1847

Character assigned 10A1

Certificate (if required)