

# ANNUAL SURVEYS.

13368

No. 186 Survey held at London Date May 6<sup>th</sup> 10 1847  
 on the By Martin Master W. H. H. H. H.  
 Tonnage 146 Built at Boston When built 1814  
 By whom built Al Bond Owners Al Bond  
 Port belonging to Shewick Destined Voyage Coastwise  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 3286 Port of Newcastle

Classed B Ship omitted

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches <u>good for class</u>	Boats
Upper Deck Beams & Fastenings <u>good for class</u>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons <u>marked as good, but defective</u>	Sails <u>well found</u>
Planksheers <u>good for class</u>	Clamps and Shelves <u>good</u>	Anchors No. of
Sheerstrakes	Ceiling <u>fair condition</u>	Cables
Topsides	Rudder <u>good</u>	Hawsers and Warps
Wales	Copper	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion This vessel was surveyed at Shewick & Newcastle & stated to have had some broken floors; upon examination from three broken floors two of them having run riden, there was an appearance of working at the end of the last beam the plank sheers & sheer strakes are slightly defective and from her general condition we are of opinion she is only fit for cargo not in their nature subject to sea damage & should be classed E

Committee Minute 11th May 1847

Character assigned F 1 W. H. H. H. H. W. H. H. H. H.  
 Certificate (if required)

No. 186 Survey held at London Date May 7<sup>th</sup> 1847  
 on the Bk Agnes Master Fox  
 Tonnage 300 Built at Chapeltown When built 1834  
 By whom built Caran Owners Caran  
 Port belonging to London Destined Voyage Unadvised  
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 11877 Port of London

Classed 4 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>3 Bower 1 Stm 2 Kedges</u>
Sheerstrakes	Ceiling	Cables <u>well found</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>45</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion From her firm & efficient condition we are of opinion she may be remain as classed

Committee Minute 11th May 1847

Character assigned Class 4 A 1 W. H. H. H. H. W. H. H. H. H.  
 Certificate (if required)



© 2019

Lloyd's Register Foundation

LON 622-70 449