

ANNUAL SURVEYS.

13379

No. 38 Survey held at London Date 10th May 1847
 on the Ship Milblain Master Currier
 Tonnage 419 Built at Greenock When built 1839
 By whom built Walker & Co Owners Walker & Co
 Port belonging to Greenock Destined Voyage Dubee
 If Surveyed Afloat or in Dry Dock in Ship Currier going to the Dock

10.0.13 May

Last Survey, No. 12079 Port of London Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>apparently Good</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>will</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>found</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>and</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides <u>Caulking overhauled</u>	Rudder	Hawsers and Warps
Wales <u>Good</u>	Copper <u>4 Metal much worn</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>now patched</u>	

General Observations and Opinion,
at present docked and yellow metal patches
she is in efficient Condition and may remain
as classed
 Committee Minute 14th May 1847
 Character assigned 10 A 1 SL

Certificate (if required)

No. 110 Survey held at London Date 11th May 1847
 on the Br Lady Sandys Master J C Pinakath
 Tonnage 290 Built at Scilly When built 1844
 By whom built Thompson Owners Thompson
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock in Caters Dock

SL

Last Survey, No. 11622 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails <u>apparently Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>sufficient</u>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers <u>Good</u>	Clamps and Shelves	Anchors No. of <u>3. 1. 2</u>
Sheerstrakes	Ceiling	Cables <u>sufficient</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>4 Metal on dry paper</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>May 1847</u>	

General Observations and Opinion,
at present bottom stripped Caulked and
sheathed with yellow metal on dry paper
is in efficient Condition and may remain
as classed
 Committee Minute 14th May 1847
 Character assigned 12 A 1 SL

Certificate (if required)