

# ANNUAL SURVEYS.

13380

No.          Survey held at London Date May 31st 1847  
 on the Wm. Wain Master Brookhurst  
 Tonnage 311 Built at Barnmouth When built 1821  
 By whom built W. Tat Owners Bottom & Co.  
 Port belonging to London Destined Voyage           
 If Surveyed Afloat or in Dry Dock (Dry dock)

No. 13380

Last Survey, No. 12305 Port of London West 52 - 7/2 Classed 12 A 1  
 The present Condition of the Good Treacils Good Windlass and Capstan efficient  
 Decks Good Breasthooks and Steason do Pumps do  
 Waterways do Transoms, Pointers, and Crutches do Boats do  
 Comings do Timbers of the Frame good when new Masts, Yards, &c. do  
 Upper Deck Beams & Fastenings None Keelsons Good Sails do  
 Lower Deck Beams & Fastenings do Clamps and Shelves do Anchors No. of 2 B.S.M. do  
 Planksheers Good Ceiling do Cables do  
 Sheerstrakes do Rudder do Hausers and Warps do  
 Topsides do Plank (Bottom) and Counter do Standing & Running Rigging do  
 Wales do  
 General Observations and Opinion, Shipped yellow metal 1847 not bottom paint from Carried and with yellow metal is in an efficient condition and may remain as shipped  
 Committee Minute 18. Nov 1847  
 Character assigned 12 A 1 1 year 1847  
 Certificate (if required)

No. 606 Survey held at London Date May 9th 1847  
 on the Ag. Cortina Master J. Grant  
 Tonnage 283 Built at Worthington When built 1840  
 By whom built          Owners Burkey  
 Port belonging to Liverpool Destined Voyage Colindale  
 If Surveyed Afloat or in Dry Dock L.P.M.

Last Survey, No. 1214 Port of Liverpool Classed 12 A 1  
 The present Condition of the Good Treacils Good Windlass and Capstan efficient  
 Decks Good Breasthooks and Steason do Pumps do  
 Waterways do Transoms, Pointers, and Crutches do Boats do  
 Comings do Timbers of the Frame good when new Masts, Yards, &c. do  
 Upper Deck Beams & Fastenings None Keelsons Good Sails do  
 Lower Deck Beams & Fastenings do Clamps and Shelves do Anchors No. of do  
 Planksheers Good Ceiling do Cables do  
 Sheerstrakes do Rudder do Hausers and Warps do  
 Topsides do Plank (Bottom) and Counter do Standing & Running Rigging do  
 Wales do  
 General Observations and Opinion, Shipped bottom painted and generally over hauled Shothed with yellow metal is in an efficient condition and may remain as shipped  
 Committee Minute 18. Nov 1847  
 Character assigned 12 A 1 1 year 1847  
 Certificate (if required)

LON 623-0003